



### Items:

- Gasket set
- Gauge 0-25 Bar
- Gauge 0-250 Bar
- 2 Direct gauge connection 1/4" - female M16x2
- Adaptor for bottle connection W25.4x1/8"
- Adaptor for bottle connection W21.7x1 1/4"
- Adaptor for Schrader valve (5/8" 18 UNF / 8V1)
- Charger
- 6 mm A/F- Allen wrench
- Adaptor M28x1.5 M16x2
- Adaptor M28x1.5 G 3/4"
- Adaptor M28x1.5 5/8"-18 UNF
- Adaptor M28x1.5 7/8"-14 UNF
- 2.5 m flexible hose (400 bar max working pressure)
- M28 x 1.5 female connection with 4 adaptors, that allow different output (M16x2, C3/4", 5/8"-18 UNF, 7/8"-14 UNF)
- Input valve with 2.5 m charging hose (up to 400 Bar) for bottle connection and relative adaptors for 2 types bottle output (W25.4x1/8" and W21.7x1/14")
- Bleed valve for pressure adjustment
- Test coupling valve for gauge connection, with 2 gauges (0-25 Bar and 0-250 Bar) and adaptors
- Additional adaptor for Schrader valve connection
- Gasket set and 6 mm A/F Allen wrench